
Supplemental Information for 264-398 Front Shock Kit (Replacement) MG TD originally fitted with Armstrong Shocks* MG TF



List of Component Parts

| | Liet of Component 1 arts | | | | | | | | | | |
|-----|--------------------------|----------|---------------------------------------|----|--------|---|--|--|--|--|--|
| Ref | Moss US | Moss UK | Description | Qu | antity | | | | | | |
| 1a | 264-360 | GSA119 | Lever Shock, Front, New | 2 | Each | | | | | | |
| 1b | 263-440 | 1G4349 | Fulcrum Pin, upper suspension link | 2 | Each | Hole for cotter pin | | | | | |
| 1c | 310-331 | 310-331 | Nut, slotted, 7/16" UNF (modified) | 2 | Each | | | | | | |
| 1d | 264-071 | 264-071 | Distance Tube (modified) | 2 | Each | | | | | | |
| 1e | 264-010 | AAA1324 | Seal Support, suspension link | 4 | Each | | | | | | |
| 1f | 324-510 | AAA1390 | Thrust washer, hardened, 1.25" OD | 4 | Each | | | | | | |
| 1g | 264-181 | 264-181 | Suspension Link, upper R/H (modified) | 1 | Each | | | | | | |
| 1g | 264-191 | 264-191 | Suspension Link, upper L/H (modified) | 1 | Each | Shortened to fit between the MGB shock arms | | | | | |
| 1h | 281-388 | ACG4030K | Seal Set (4 pin & 8 link seals) | 1 | Set | | | | | | |
| | 325-105 | PC10 | Cotter Pin | 2 | Each | For slotted nut | | | | | |
| | 980-376 | 980-376 | Supplemental Information | 1 | Each | This Document | | | | | |

Not included: Bolt, securing shock. Re-use your old bolts or order 8 of the 320-590 bolts.

^{*} These will not fit an MG TD that was originally fitted with Girling shocks. MG TDs must have the clearance "bump" in the front fender to clear shock body.

41

| Space for Your I | Notes | | | |
|------------------|-------|--|--|--|
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |

At this time, we do not have installation instructions because the assembly is so similar to the process covered in your workshop manual.

Any suggestions that you may have that will improve the information (especially detailed installation notes not in the workshop manual) are welcome. Please use the simple email form on the "Contact Us" page on the Moss website: http://www.mossmotors.com/AboutMoss/ContactUs.aspx

If you prefer, you may call our Technical Services Department at 805-681-3411. So many people call us for help that we are often not able to answer the calls as fast as we'd like, and you may be asked to leave a message. We apologize in advance for the inconvenience. We will get back to you within 2-4 business days.



Moss Motors, Ltd.

440 Rutherford Street, Goleta, California 93117
In the US & Canada Toll Free (800) 667-7872 FAX (805) 692-2510 (805) 681-3400
Moss Europe Ltd.

Hampton Farm Industrial Estate, Hampton Road West, Hanworth Middlesex, TW13 6DB In the UK: 020-8867-2020 FAX:- 020-8867-2030

Instruction Sheet Moss 264-398 September 2012